Oil Field Environmental Incident Summary

Responsible Party: SM ENERGY COMPANY **Well Operator:** SM ENERGY COMPANY

Well Name: WRRMU 8-21

Field Name: ROUGH RIDER Well File #: 5994

Date Incident:8/11/2014Time Incident:16:30Facility ID Number:County:MCKENZIETwp:145Rng:101Sec:21Qtr:

Location Description: Well access road

Submitted By: Luke Studer Received By:

Contact Person: Luke Studer

PO BOX 7168

BILLINGS, MT 59103-7168

General Land Use: Other - Described Above Affected Medium: Topsoil

Distance Nearest Occupied Building: 5 Mile **Distance Nearest Water Well:** 5 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 5 Barrels 0 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 3/9/2015 Clean Up Concluded: 8/12/2014

Risk Evaluation:

None

Areal Extent:

N/A

Potential Environmental Impacts:

None

Action Taken or Planned:

Salt water flowline was flushed with fresh water and shut in while clean up can be completed.

Wastes Disposal Location: Contaminated soil will be hauled to an approved disposal.

Agencies Involved:

Updates

Date: 8/13/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to a pipeline leak. Followup is necessary.

Date: 8/20/2014 Status: Inspection Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 7:30, off site 8:10; overcast, lightning, south wind at 5 mph, 69 degrees. Remote location; turned on to road with "closed road" sign in Twp 145, Rng 101, Sec 21 and headed west. Walked entire well site and pipeline going west into land posted by the Ruby Ranch. All very orderly and clean. No indication of spill. Took pictures. Beautiful vista.